





Parameter

#			
P01		PID slow () (4)	0 = 2P, 1.0 K 1 = 2P, 0.5 K 2 = PID fast () 4 = PID slow ()
P02	Max °C	30 °C	P03...30 °C
P03	Min °C	5 °C	5 °C...P02
End	→ Exit		

